Contents

1. Surface texture: two-dimensional 1
1.1 Introduction 3
1.2 Establishing the ***Ra*** numerical value of surface texture from the production process 8
1.3 Surface texture roughness comparison blocks and precision reference specimens 8
1.4 The basic operating principle of the pick-up, its stylus and skid 9
1.5 Filters and cut-off 13
1.6 Measuring lengths 15
1.7 Filtering effects (λs, λc **and** λf) 19
1.8 Geometrical parameters 21
1.9 Surface profile parameters 22
1.9.1 Amplitude parameters (peak-to-valley) 23
1.9.2 Amplitude parameters (average of ordinates) 24
1.9.3 Spacing parameters 29
1.9.4 Hybrid parameters 29
1.9.5 Curves and related parameters 29
1.9.6 Overview of parameters 32
1.10 Auto-correlation function 32
1.11 Appearance of peaks and valleys 34
1.12 Stylus-based and non-contact systems 37
1.12.1 Pick-up 40
1.12.2 Skid or pick-up operation 43
1.12.3 Portable surface texture instruments 45
1.12.4 Surface form measurement 46
1.12.5 Non-contact systems 50
1.13 Nanotopographic instruments 63

2. Surface texture: three-dimensional 69
2.1 Introduction 71
2.1.1 Stylus speed and dynamics 72
2.1.2 Envelope and mean systems 74
2.1.3 Three-dimensional characterisation 74
2.2 Three-dimensional analysis software 79
2.2.1 Functional 3-D performance 85
2.3 Portable three-dimensional measuring instruments 89
2.4 Fractal techniques 90

2.4.1 Topological characterisation 90
2.5 Textured metal sheets 93
2.6 Surface topography characterisation by neural networks 94
2.7 Non-contact measurement 96

3. Surface microscopy 101
3.1 Introduction 103
3.2 Scanning electron microscope 105
3.2.1 Energy-dispersive X-ray spectrometer 112
3.2.2 Transmitted electron image 114
3.3 Transmission electron microscope 114
3.3.1 Transmission electron microscopy: general application 119
3.4 Atomic force microscope 119
3.4.1 Criteria for using scanning probe microscopes 121
3.4.2 Atomic force microscope: operating principle 123
3.4.3 Atomic force/scanning probe microscope: applications 125
3.4.4 Ultrasonic force microscope: developments 128
3.5 X-ray photoelectron spectroscopy 130

4. Roundness and cylindricity 135
4.1 Introduction 137
4.1.1 Roundness measurement: basic approach 143
4.2 Roundness: measuring instruments 144
4.2.1 Types of instrument 145
4.2.2 Spindle and bearings 146
4.3 Methods of measurement 150
4.3.1 Assessment of part geometry 152
4.4 Display and interpretation 156
4.5 Roundness measurement from the display 157
4.5.1 Roundness reference circles 159
4.5.2 Numerical value of roundness 160
4.5.3 Filtering and harmonics 162
4.6 Geometric roundness parameters 171
4.6.1 Cylindricity 173
4.6.2 Cylindricity measurement techniques 176
4.6.3 Cylindrical measurement problems 177
4.7 Non-contact spherical and roundness assessment 178
4.7.1 Sphericity interferometer 178
4.7.2 Spherical and roundness assessment by error separation 180

5. Machined surface integrity 185
5.1 Introduction 187
5.2 The machined surface 189
5.2.1 Residual stresses in machined surfaces 192
5.2.2 Tribological cutting effect on surface 196

5.2.3 Micro-hardness testing 198
5.2.4 Surface cracks and "white layers" 203
5.2.5 Machined surface topography 211
5.2.6 Machined roundness 220
5.2.7 Power spectrum analysis of machined surfaces 234
5.2.8 Manufacturing process envelopes 236
5.3 Surface engineering 243

6. Quality and calibration techniques 249
6.1 Size and scale 252
6.2 Predictable accuracy: its evolution 253
6.3 Traceability of measurement 255
6.4 Measurement uncertainty 262
6.5 Calibration: surface texture 274
6.5.1 Surface texture artefacts 274
6.5.2 Stylus damage 281
6.6 Calibration: roundness 282
6.7 Probing uncertainty: roundness and form 288
6.8 Nanotechnology instrumentation: now and in the future 289

Appendices 297

Appendix A – Previous and some current surface texture parameters 299

Appendix B – Amplitude–wavelength analysis: "Stedman diagrams" 317

Appendix C – Surface texture and roundness: calibration diagrams and photographs 320

Appendix D – Hardness conversion chart 325

Index 327