Contents

Movies accompanying the text are located at: www.sitemaker.umich.edu/was.

Part I Radiation Damage

1 The Radiation Damage Event 3
1.1 Neutron–Nucleus Interactions 4
1.1.1 Elastic Scattering 4
1.1.2 Inelastic Scattering 11
1.1.3 (n, 2n) Reactions 14
1.1.4 (n, γ) Reactions 15
1.2 Interactions Between Ions and Atoms 17
1.2.1 Interatomic Potentials 17
1.2.2 Collision Kinematics 24
1.3 Ionization Collisions 44
1.3.1 Energy Loss Theory 44
1.3.2 Range Calculations 57
Nomenclature 66
Problems 68
References 71

2 The Displacement of Atoms 73
2.1 Elementary Displacement Theory 73
2.1.1 Displacement Probability 74
2.1.2 The Kinchin and Pease Model for Atom Displacements . . . 75
2.1.3 The Displacement Energy 78
2.1.4 The Electron Energy Loss Limit 83
2.2 Modifications to the K–P Displacement Model 85
2.2.1 Consideration of E_d in the Energy Balance 85
2.2.2 Realistic Energy Transfer Cross Sections 86
2.2.3 Energy Loss by Electronic Excitation 87
2.2.4 Effects of Crystallinity 91
2.3 The Displacement Cross Section 105
2.3.1 Elastic Scattering 106
2.3.2 Inelastic Scattering 107
2.3.3 (n, 2n) and (n, γ) Displacements 107
2.3.4 Modifications to the K–P Model and Total Displacement Cross Section 108

2.4 Displacement Rates 109
2.5 Correlation of Property Changes and Irradiation Dose 113
2.6 Displacements from Charged Particle Irradiation 115
Nomenclature 119
Problems 121
References 123

3 The Damage Cascade 125
3.1 Displacement Mean Free Path 125
3.2 Primary Recoil Spectrum 126
3.3 Cascade Damage Energy and Cascade Volume 131
3.4 Computer Simulations of Radiation Damage 133
3.4.1 Binary Collision Approximation (BCA) Method 133
3.4.2 Molecular Dynamics (MD) Method 136
3.4.3 Kinetic Monte Carlo (KMC) Method 138
3.5 Stages of Cascade Development 140
3.6 Behavior of Defects within the Cascade 143
Nomenclature 152
Problems 153
References 154

4 Point Defect Formation and Diffusion 155
4.1 Properties of Irradiation-Induced Defects 155
4.1.1 Interstitials 155
4.1.2 Multiple Interstitials 160
4.1.3 Interstitial–Impurity Complexes 161
4.1.4 Vacancies 162
4.1.5 Multiple Vacancies 162
4.1.6 Solute–Defect and Impurity–Defect Clusters 162
4.2 Thermodynamics of Point Defect Formation 164
4.3 Diffusion of Point Defects 167
4.3.1 Macroscopic Description of Diffusion 168
4.3.2 Mechanisms of Diffusion 169
4.3.3 Microscopic Description of Diffusion 172
4.3.4 Jump Frequency, Γ 174
4.3.5 Jump Frequency, ω 176
4.3.6 Equations for D 177
4.4 Correlated Diffusion 180
4.5 Diffusion in Multicomponent Systems 182
4.6 Diffusion along High Diffusivity Paths 184
Nomenclature 187
Problems 188
References 190

5 Radiation-Enhanced and Diffusion Defect Reaction Rate Theory . . . 191
5.1 Point Defect Balance Equations . . . 192
5.1.1 Case 1: Low Temperature, Low Sink Density . . . 194
5.1.2 Case 2: Low Temperature, Intermediate Sink Density . . . 196
5.1.3 Case 3: Low Temperature, High Sink Density . . . 197
5.1.4 Case 4: High Temperature . . . 199
5.1.5 Properties of the Point Defect Balance Equations . . . 201
5.1.6 Deficiencies of the Simple Point Defect Balance Model . . . 203
5.2 Radiation-Enhanced Diffusion . . . 203
5.3 Defect Reactions . . . 206
5.3.1 Defect Production . . . 209
5.3.2 Recombination . . . 210
5.3.3 Loss to Sinks . . . 210
5.3.4 Sink Strengths . . . 211
5.4 Reaction Rate-Controlled Processes . . . 211
5.4.1 Defect–Void Interaction . . . 211
5.4.2 Defect–Dislocation Interaction . . . 212
5.5 Diffusion-Limited Reactions . . . 212
5.5.1 Defect–Void Reactions . . . 213
5.5.2 Defect–Dislocation Reactions . . . 215
5.6 Mixed Rate Control . . . 217
5.7 Defect–Grain Boundary Reactions . . . 218
5.8 Coherent Precipitates and Solutes . . . 219
Nomenclature . . . 222
Problems . . . 223
References . . . 227

Part II Physical Effects of Radiation Damage

6 Radiation-Induced Segregation . . . 231
6.1 Radiation-Induced Segregation in Concentrated Binary Alloys . . . 233
6.1.1 Solution to the Coupled Partial Differential Equations . . . 239
6.1.2 Interstitial Binding . . . 240
6.1.3 Solute Size Effect . . . 241
6.1.4 Effect of Temperature . . . 242
6.1.5 Effect of Dose Rate . . . 245
6.2 RIS in Ternary Alloys . . . 246
6.3 Effect of Local Composition Changes on RIS . . . 250
6.4 Effect of Solutes on RIS . . . 253
6.5 Examples of RIS in Austenitic Alloys . . . 256
6.6 RIS in Ferritic Alloys . . . 259
Nomenclature . . . 263
Problems . . . 264
References . . . 265

7 Dislocation Microstructure 267
7.1 Dislocation Lines 267
7.1.1 Dislocation Motion 270
7.1.2 Description of a Dislocation 274
7.1.3 Displacements, Strains and Stresses 276
7.1.4 Energy of a Dislocation 280
7.1.5 Line Tension of a Dislocation 281
7.1.6 Forces on a Dislocation 283
7.1.7 Interactions Between Dislocations 289
7.1.8 Extended Dislocations 292
7.1.9 Kinks and Jogs 294
7.2 Faulted Loops and Stacking Fault Tetrahedra 294
7.3 Defect Clusters 298
7.3.1 Fraction of Defects Forming Clusters 298
7.3.2 Types of Clusters 300
7.3.3 Cluster Mobility 304
7.4 Extended Defects 306
7.5 Effective Defect Production 311
7.6 Nucleation and Growth of Dislocation Loops 313
7.6.1 Loop Nucleation 313
7.6.2 Clustering Theory 319
7.6.3 Production Bias-Driven Cluster Nucleation 321
7.7 Dislocation Loop Growth 325
7.8 Recovery 329
7.9 Evolution of the Interstitial Loop Microstructure 332
Nomenclature 335
Problems 338
References 341

8 Irradiation-Induced Voids and Bubbles 343
8.1 Void Nucleation 343
8.1.1 Equilibrium Void Size Distribution 345
8.1.2 Void Nucleation Rate 348
8.1.3 Effect of Inert Gas 355
8.1.4 Void Nucleation with Production Bias 362
8.2 Void Growth 365
8.2.1 Defect Absorption Rates and Concentrations at Sink Surfaces 366
8.2.2 Point Defect Balances 370
8.3 Void Growth Equation 372
8.3.1 Temperature Dependence 377
8.3.2 Dose Dependence 380
8.3.3 Role of Dislocations as Biased Sinks 384
8.3.4 Dose Rate Dependence 385
8.3.5 Irradiation Variable Shifts 388

8.3.6 Stress Dependence 393
8.3.7 Effect of RIS 397
8.3.8 Effect of Production Bias 399
8.3.9 Void Lattices 402
8.3.10 Effect of Microstructure and Composition 404
8.3.11 Effect of Reactor Operating History 409
8.4 Bubble Growth 415
8.4.1 Bubble Mechanics 415
8.4.2 Growth Law 418
8.4.3 Bubble Growth by Dislocation Loop Punching 421
8.4.4 Bubble Lattices 422
8.4.5 Helium Production 423
Nomenclature 423
Problems 427
References 430

9 Phase Stability Under Irradiation 433
9.1 Radiation-Induced Segregation and Radiation-Induced Precipitation 433
9.2 Recoil Dissolution 436
9.3 Radiation Disordering 445
9.4 Incoherent Precipitate Nucleation 450
9.5 Coherent Precipitate Nucleation 455
9.6 Metastable Phases 460
9.6.1 Order–Disorder Transformations 461
9.6.2 Crystal Structure Transformations 461
9.6.3 Quasicrystal Formation 463
9.7 Amorphization 463
9.7.1 Heat of Compound Formation and Crystal Structure Differences 464
9.7.2 Solubility Range of Compounds and Critical Defect Density 467
9.7.3 Thermodynamics and Kinetics of Amorphization 470
9.8 Phase Stability in Reactor Core Component Alloys 480
Nomenclature 484
Problems 487
References 488

10 Unique Effects of Ion Irradiation 491
10.1 Ion Irradiation Techniques 491
10.2 Composition Changes 494
10.2.1 Sputtering 495
10.2.2 Gibbsian Adsorption 501
10.2.3 Recoil Implantation 503
10.2.4 Cascade (Isotropic, Displacement) Mixing 506

10.2.5 Combination of Processes Affecting Surface Compositional Changes . . . 518
10.2.6 Implant Re-Distribution During Ion Implantation . . . 522
10.3 Other Effects of Ion Implantation . . . 525
10.3.1 Grain Growth . . . 525
10.3.2 Texture . . . 527
10.3.3 Dislocation Microstructure . . . 528
10.4 High Dose Gas Loading: Blistering and Exfoilation . . . 530
10.5 Solid Phases and Inert Gas Bubble Lattices . . . 535
Nomenclature . . . 537
Problems . . . 540
References . . . 543

11 Simulation of Neutron Irradiation Effects with Ions . . . 545
11.1 Motivation for Using Ion Irradiation as a Surrogate for Neutron Irradiation . . . 545
11.2 Review of Aspects of Radiation Damage Relevant to Ion Irradiation 547
11.3 Particle Type Dependence of RIS . . . 550
11.4 Advantages and Disadvantages of the Various Particle Types . . . 557
11.4.1 Electrons . . . 558
11.4.2 Heavy Ions . . . 562
11.4.3 Protons . . . 564
11.5 Irradiation Parameters for Particle Irradiations . . . 565
11.6 Emulation of Neutron Irradiation Damage with Proton Irradiation . . 567
Nomenclature . . . 574
Problems . . . 575
References . . . 576

Part III Mechanical Effects of Radiation Damage

12 Irradiation Hardening and Deformation . . . 581
12.1 Elastic and Plastic Deformation . . . 581
12.1.1 Elasticity . . . 581
12.1.2 Plasticity . . . 587
12.1.3 Tension Test . . . 589
12.1.4 Yield Strength . . . 592
12.2 Irradiation Hardening . . . 594
12.2.1 Source Hardening . . . 595
12.2.2 Friction Hardening . . . 597
12.2.3 Superposition of Hardening Mechanisms . . . 606
12.2.4 Hardening in Polycrystals . . . 612
12.2.5 Saturation of Irradiation Hardening . . . 613
12.2.6 Comparison of Measured and Predicted Hardening . . . 617
12.2.7 Radiation Anneal Hardening . . . 620

12.2.8 The Correlation Between Hardness and Yield Strength 622
12.3 Deformation in Irradiated Metals 626
12.3.1 Deformation Mechanism Maps 630
12.3.2 Localized Deformation 632
Nomenclature 636
Problems 638
References 640

13 Fracture and Embrittlement 643
13.1 Types of Fracture 643
13.2 The Cohesive Strength of Metals 644
13.3 Fracture Mechanics 647
13.4 Fracture Mechanics Tests 653
13.5 Elastic-Plastic Fracture Mechanics 655
13.6 Brittle Fracture 658
13.7 Irradiation-Induced Embrittlement in Ferritic Steels 664
13.7.1 Notched Bar Impact Testing 664
13.7.2 DBTT and Reduction in the Upper Shelf Energy 666
13.7.3 Master Curve Approach 669
13.7.4 Factors Affecting the Degree of Embrittlement 673
13.7.5 Embrittlement of Ferritic-Martensitic Steels 677
13.7.6 Annealing and Re-Irradiation 678
13.7.7 Fatigue 679
13.8 Fracture and Fatigue of Austenitic Alloys at Low to Intermediate Temperatures 685
13.8.1 Effect of Irradiation on Fracture Toughness 686
13.8.2 Effect of Irradiation on Fatigue 689
13.9 High-Temperature Embrittlement 690
13.9.1 Grain Boundary Voids and Bubbles 692
13.9.2 Grain Boundary Sliding 697
13.9.3 Grain Boundary Crack Growth 700
13.9.4 Fracture Mechanism Maps 703
Nomenclature 703
Problems 705
References 707

14 Irradiation Creep and Growth 711
14.1 Thermal Creep 712
14.1.1 Dislocation Creep 716
14.1.2 Diffusional Creep 723
14.2 Irradiation Creep 725
14.2.1 Stress-Induced Preferential Nucleation of Loops (SIPN) . . . 726
14.2.2 Stress-Induced Preferential Absorption (SIPA) 729
14.2.3 Climb and Glide due to Preferential Absorption (PAG) 731
14.2.4 Climb and Glide Driven by Dislocation Bias 733

14.2.5 Transient Creep 734
14.2.6 Loop Unfaulting 738
14.2.7 Recovery Creep 739
14.2.8 Diffusional Creep: Why There is no Effect of Irradiation . . 740
14.2.9 Comparison of Theory with Creep Data 741
14.2.10 Irradiation-Modified Deformation Mechanism Map 744
14.3 Irradiation Growth and Creep in Zirconium Alloys 746
14.3.1 Microstructure of Irradiated Zirconium Alloys 747
14.3.2 Irradiation Growth 750
14.3.3 Irradiation Creep 753
Nomenclature 758
Problems 760
References 762

15 Environmentally Assisted Cracking of Irradiated Metals and Alloys . 765
15.1 Stress Corrosion Cracking: A Tutorial 768
15.1.1 SCC Tests 770
15.1.2 SCC Processes 772
15.1.3 Metallurgical Condition 774
15.1.4 Crack Initiation and Crack Propagation 774
15.1.5 Mechanisms of Stress Corrosion Cracking 783
15.1.6 Predictive Model for Crack Propagation 786
15.1.7 Mechanical Fracture Models 788
15.1.8 Corrosion Fatigue 790
15.1.9 Hydrogen Embrittlement 790
15.2 Effects of Irradiation on Water Chemistry 791
15.2.1 Radiolysis and its Effect on Corrosion Potential 791
15.2.2 Effect of Corrosion Potential on IASCC 794
15.3 Service and Laboratory Observations of Irradiation Effects on SCC . 797
15.3.1 Austenitic Alloys 797
15.3.2 Ferritic Alloys 802
15.4 Mechanisms of IASCC 805
15.4.1 Grain Boundary Chromium Depletion 805
15.4.2 Irradiation Hardening 806
15.4.3 Deformation Mode 807
15.4.4 Selective Internal Oxidation 809
15.4.5 Irradiation-Induced Creep 809
Nomenclature 809
Problems 811
References 812

Index 815